


VCOM install for WIN8

- 1 Install vcomsetup.exe
- 2 Install wincap.exe
 - 2.1 Path C:\\Program Files\\IC Plus corp\\VCOM\\wincap.exe
 - 2.2 Right-click on the wincap.exe, choose the content, compatibility choice for Windows 7, As shown in the figure below :



- 2.3 One-click installation
- 3 After the Wincap.exe installation is complete, can be normal use VCOM.